Change Proposal – F40/02 (Page 1 of 2)

CP No: 757 (mandatory by BSCCo)

Title Missing Timescale in PSL110 Section 5.3.2

Description of Change (mandatory by originator)

The Service Level for Serial 1 in Section 5.3.2 of PSL110, "SVA Meter Operation", currently states:

- i) 95% rectified within 5 WD of notification;
- ii) 99% rectified within WD of notification.

There is no timescale defined in ii) above.

Proposed Solution(s) (mandatory by originator)

Amend the Service Level to:

ii) 99% rectified within 15 WD of notification.

Justification for Change (mandatory by originator)

No timescale is specified in the Service Level. 15 WD is the timescale utilised in PARMS Monitoring.

Other Configurable Items Potentially Affected by Proposed Solution(s) (optional by BSCCo)

None

Impact on Core Industry Documents (optional by originator)

None

Related Changes and/or Projects (mandatory by BSCCo)

None

Change	Proposal – F40/01 (Page 2 of 2)	CP No: (mandatory by BSCCo)
Originator's Details:		•
BCA Name		
Organisation		
Email Address		
Date 05/02/2002		
Attachments: N* (delete as appropriate)	(If Yes, No. of Pages attached:)	