

Change Proposal – F40/01 (Page 1 of 2)	S21797 CP No: 572 <i>(mandatory by BSCCo)</i>
Title <i>(mandatory by originator)</i> Changes to BSCP01	
Description of Change <i>(mandatory by originator)</i> This Change Proposal has been raised to address inconsistencies initially identified by the NETA Programme and subsequently reviewed and deemed to be valid by the Inconsistency Review Project (IRP CP013). Inconsistencies SAA_02 and SAA_27 Errors relating to the SAA have been identified in BSCP01 v.2. In several sections, 'Quiescent Physical Notification' has been omitted or misplaced, required a change in the BSCP.	
Proposed Solution(s) <i>(mandatory by originator)</i> Change BSCP01 sections 3.2, 4.1.3, 4.1.8, 5.1 and 5.2 to include Quiescent Physical Notification along with Final Physical Notification. Section 4.1.6 should also be changed so the QPN is sent at the same time as the FPN, i.e. no later than 15 minutes after Gate Closure instead of 5 minutes.	
Justification for Change <i>(mandatory by originator)</i> To remove inconsistencies between BSCP01 v.2.0 and SAA URS v.2.4 sections I003 & I004	
Other Configurable Items Potentially Affected by Proposed Solution(s) <i>(optional by BSCCo)</i>	
Impact on Core Industry Documents <i>(optional by originator)</i>	
Related Changes and/or Projects <i>(mandatory by BSCCo)</i>	
Originator's Details: BCA Name... Inconsistency Review Project..... Organisation Email Address Date24 th May 2001..... Organisation	
Attachments: Y/N* (If Yes, No. of Pages attached:.....) <i>(delete as appropriate)</i>	